

DEPARTMENT OF TRANSPORTATION -Toll Bridge Program

333 Burma Rd.
Oakland, CA 94607
(510) 622-5660, (510) 286-0550 fax



*Flex your power
Be energy efficient!*

March 11, 2011

Contract No. 04-0120F4
04-SF-80-13.2 / 13.9
Self-Anchored Suspension Bridge
Letter No. 05.03.01-009219

Brian A Petersen
Project Executive
American Bridge/Fluor, A JV
375 Burma Road
Oakland, CA 94607

Dear Brian Petersen,

Authority to Proceed – CCO 189 - Bikepath Handrail - Railing Divider

Per conversations at the March 08, 2011 Coordination Meeting, the Department is providing direction to ABF regarding the following items of work on the bikepath handrail railing divider:

1. Do not cut the handhole on the vertical post of the divider rail.
2. Do not install the light fixture housing.
3. Do not apply a top coat of the Interfine 979 over the galvanized railing divider.

This work will be performed locally after the shipment has arrived to the job site from the fabrication shop at ZPMC.

In accordance with Standard Specifications Section 4-1.03, "Changes," authorization is provided to proceed with this change. Compensation for this work will be provided under CCO 189.

If you have questions, please contact William Casey.

Sincerely,

A handwritten signature in blue ink, appearing to read "William S. Casey".

WILLIAM S. CASEY
Construction Manager (OBG)

For: PETER SIEGENTHALER
Resident Engineer

file: 05.03.01, 49.189, 55.1789